

 <p style="text-align: center;">State of Ohio Weatherization Program Standards</p>	Section	<b>MOBILE HOME FINAL INSPECTION</b>
	Subject	<b>Ceiling</b>

*ELECTRICAL SYSTEM SAFETY 802-3.1*

Ensure that any unsafe wiring problems have been corrected. Ensure that any aluminum wiring is not nicked, loose or exposed.

**wiring**  
802-3.1a

Ensure that electrical devices have the required safety clearance shielding.

**clearance shielding**  
802-3.1b

Ensure that circuits are properly fused. Explain to the customer the importance of properly fused circuits.

**fuse size**  
802-3.1c

CEE
-----

*CEILING 802-3.2*

Ensure that interior moisture problems have been corrected.

**interior ceiling  
moisture problems**  
802-3.2a

Ensure that the ceiling is safely supporting the insulation.

**ceiling support**  
802-3.2b

Ensure that the connection of the ceiling and the flue vent is completely sealed.

**seal connection**  
802-3.2c

*INSULATION 802-3.3*

Ensure that the proper amount of insulation was installed in the roof cavity.

**insulation amount**  
802-3.3a

Ensure that there are no holes or gaps left in the insulation.

**complete coverage**  
802-3.3b

Ensure that attic insulation has not drifted into inappropriate areas, such as around recessed lights.

**blocking verification**  
802-3.3c

Ensure that attic insulation is not obstructing any existing open vents. Ensure that no roof venting was installed.

**vents**  
802-3.3d

Ensure that any damaged trusses or other attic structural members have been repaired or replaced.

**damaged trusses**  
802-3.3e

**moisture in insulation**  
802-3.3f

Ensure that there is no moisture in the attic insulation.

**proper finish**  
802-3.3g

Ensure that any building components removed, lifted or drilled, for the installation of attic insulation, have been returned to proper condition.