



State of Ohio  
Weatherization Program  
Standards

Section **MOBILE HOME  
FINAL INSPECTION**

Subject **Belly**

*UNDER THE MOBILE HOME 802-5.1*

Ensure that draftproofing was not installed or repaired with HWAP funds.

**draftproofing**  
802-5.1a

Ensure that holes in the bellyboard have been patched to stop air movement effectively.

**patched bellyboard**  
802-5.1b

Ensure that moisture problems under or around the mobile home have been corrected, if possible.

**ground moisture/  
drainage**  
802-5.1c

Ensure that any crawlspace that is enclosed with draftproofing has a 6 mil polyethylene vapor barrier installed effectively. If there is excessive moisture present, ensure that adequate closeable venting is present.

**ground vapor barrier**  
802-5.1d

Ensure that insulation has been installed to the proper density, and that there is complete coverage.

**insulation/proper  
density**  
802-5.1e

Ensure that water and sewage lines have been treated, as necessary.

**water/sewer**  
802-5.1f

Ensure that the duct system has been thoroughly sealed.

**duct system**  
802-5.1g

Ensure that combustion air intakes are not blocked or obstructed.

**combustion air  
intakes**  
802-5.1h

Ensure that all exhaust appliances are exhausted to the outside and have positive dampers.

**exhaust fans**  
802-5.1i