

 <p style="text-align: center;">State of Ohio Weatherization Program Standards</p>	Section	<b>BUILDING SHELL FINAL INSPECTION</b>
	Subject	<b>Sidewalls</b>

*HAZARDS 402-4.1*

Observe all necessary measures to ensure personal health and safety during the final inspection.

**health and safety**  
402-4.1a

Ensure that allowable repairs have been made to bare, frayed, or uninsulated wires leading to the house.

**electrical hazards**  
402-4.1b

Ensure that exterior flues, chimneys, gas or oil lines, fuel tanks, and plumbing lines have not been damaged and are in operable condition.

**pipng hazards**  
402-4.1c

*SIDEWALL CONDITION 402-4.2*

Ensure that asbestos siding has not been drilled.

**asbestos siding**  
402-4.2a

Ensure that severely deteriorated window or door components have been repaired or replaced. Ensure that missing glass has been replaced.

**exterior doors &  
windows**  
402-4.2b

Ensure that exterior moisture damaged areas, such as missing or rotted siding, have been repaired or replaced.

**moisture damage**  
402-4.2c

Ensure that exposed structural components have been addressed so that the insulation is contained in the wall cavities.

**structural integrity**  
402-4.2d

Ensure that insulation has been properly installed in all required wall cavities.

**insulation installation**  
402-4.2e

Ensure that the exterior drill installations have been properly finished and that the final appearance is as close to the original as possible.

**exterior finish**  
402-4.2f

*INTERIOR SURVEY 402-4.3*

If insulation has not been installed because of weak interior wall surfaces, verify the noted surfaces.

**interior surface**  
402-4.3a

**interior finish**  
402-4.3b

Ensure that the interior drill installations have been properly finished and that the final appearance is as close to the original as possible.

**dust and debris**  
402-4.3c

Ensure that no insulation dust or debris has been left in the house.

**interior mechanicals**  
402-4.3d

Ensure that insulation has not escaped into wall heaters, vent fans, ducts, or other mechanical or intentional penetrations.

**structural details**  
402-4.3e

Ensure that structural details such as interior soffits, pocket doors and other bypass features have been properly addressed in the insulation process. Ensure that critical framing junctures have been properly addressed.

*INSULATION 402-4.4***insulation amount**  
402-4.4a

Ensure that sidewall insulation has been installed to the proper density.

**open cavity installation**  
402-4.4b

Ensure that insulation installed in open cavities is not exposed to the living area.