



State of Ohio
Weatherization Program
Standards

Section	MOBILE HOME FINAL INSPECTION
Subject	Sidewalls

ELECTRICAL SAFETY 802-4.1

Ensure that any bare, frayed or other improper wiring has been corrected. Pay particular attention to mobile homes which have aluminum wiring.

electrical wiring
802-4.1a



EXTERIOR INSPECTION 802-4.2

Ensure that doors and door components have been repaired or replaced, if specified.

doors
802-4.2a

Ensure that missing glass has been replaced and that windows and window components have been repaired, if specified.

windows
802-4.2b

Ensure that any moisture problem affecting the sidewalls has been addressed.

moisture problems
802-4.2c

Ensure that siding panels have been properly reattached if they have been removed or loosened for the addition of sidewall insulation. Ensure that any missing siding has been replaced.

siding panels
802-4.2d

Ensure that stick-built additions have received sidewall insulation, if required.

additions
802-4.2e

INTERIOR WALL SURFACES 802-4.3

Ensure that switchbox and outlet covers and any interior trim removed to install sidewall insulation have been properly reinstalled.

outlet covers/trim
802-4.3a

If there are primary air leakage sites, ensure that any missing or deteriorated interior wall surfaces have been repaired or replaced.

repair
802-4.3b

Ensure that the clothes dryer is vented to the outside with an operable positive damper. Ensure that the vent fans have an operable positive damper.

clothes dryer
802-4.3c

ceiling height changes
802-4.3d

Ensure that areas of ceiling height changes, dropped soffits, etc., have been properly addressed.

SIDEWALL INSULATION 802-4.4

insulation
802-4.4a

Ensure that sidewall insulation is installed correctly and effectively.